



*Quality and Value
Through Engineering*

- ◆ VSEA/Varian High Current
- ◆ 120-10
- ◆ 160-10
- ◆ 180-10

VSEA – IMPLANTER PARTS
120-10, 160-10, 180-10 Series High Current

Signet's Filament Connector



Signet Products 30-9746

One Signet Products 30-9746, pictured to the right, can replace VSEA/Varian's filament connector rod assembly that consists of the 6 pieces pictured to the left. Signet's Filament Connector Rod employs the same processed screw that is used by VSEA/Varian in their 3000 series (i.e. CF/DF & 350D) implanters.

Our 30-9746 replaces the following parts:

Qty	OEM Part #	Description
1	F9746001	Filament Connector Rod
1	F9745001	Filament Clamp
2	1231200808	8-32 X 1/2 SHC Screw
2	1312206000	# 8 Hex Nut

One Signet Products part number replaces four VSEA/Varian part numbers and it is easier to install. Dealing with one part number rather than four saves time in Purchasing, Receiving, Stores, Maintenance, Equipment Engineering and Accounts Payable.

Ref. = Design Alteration of OEM Part

Signet Products Inc.

2 Davis Drive
Belmont, CA 94002
Revised 03/12/03

Phone 650 592-3575
Fax 650 592-7223
e-mail sales@signetproducts.com
Web www.signetproducts.com