

Quality and Value Through Engineering

- Eaton/Nova 3204
- Eaton/Nova 3206
- Eaton/Nova 6200

Why use both these when .....



Signet Part Numbers 44-0005 and 44-0015

AXCELIS - 3204, 3206 & 6200 SKM ARC CHAMBER ASSEMBLY

## Signet Combo Insulator



## Signet PN 40-0005 or 41-0005

Signet's Combo Insulators replaces both the inner and outer insulators in the SKM Source. (Signet part numbers 44-0005 and 44-0015). You only have one part to stock and assemble rather than two. Reports of field performance have been excellent and one Combo Insulator costs a third less than the original pair of insulators. The Signet Combo Insulator is now available in either Boron Nitride (BN) or Alumina  $(AL_2O_3)$ .

Signet PN	OEM PN	Qty	Description
40-0005	(not available)	1	Insulator, Combo, BN
41-0005	(not available)	1	Insulator, Combo, Al <sub>2</sub> O <sub>3</sub>
44-0005	3111-0005-0001	1	Insulator, Outer
44-0015	3113-0015-0001	1	Insulator, Inner

Signet will also continue to supply both Part Numbers 44-0005 and 44-0015 insulators.