

Quality and Value Through Engineering

Riber R49

MBE/MOCVD

Riber R49

Signet R49 Shutter Blade



Signet Part 55-0102 Shutter Blade

Depending upon process conditions, shutter blades can be one of the components in the R49 chamber that requires frequent replacement. The OEM replacement can be very expensive.

Due to Signet's batch manufacturing process, the Signet R49 shutter blade is typically a great deal less expensive that those offered by the OEM.

Signet Products Inc. supplies parts that replace OEM consumable parts. Whenever possible, they are engineered to improve performance and or extend service life. A "Ref." following an OEM part number indicates our part is an improved design related to this OEM part.

Go to our website at: <u>www.signetproducts.com</u> Follow the MBE MOCVD link

Signet Products Inc.

2 Davis Drive Belmont, CA 94002 PDS55-0102 Rev. 08/14/06 MBE/MOCVD Parts Sales Contact Ross Davies (774) 847-9028 **Ref. = Design Alteration of OEM Part**

Phone 650 592-3575 Fax 650 592-7223 e-mail <u>sales@signetproducts.com</u> Web <u>www.signetproducts.com</u>